


Eastern Analytical Services, Inc.
Water Sample Report

RE: Edgemont - Seely Place School

Date Collected: 04/22/2021
 Collected By: Nicholas Coon
 Date Received: 04/23/2021
 Date Analyzed: 04/28/2021
 Analyzed By: Ernest Sanchez
 Signature: 
 Analyte: Pb Water
 Analytical Method: EPA 200.9
 NYS Lab Number: 10851

Client: RegCom
 245 Albany Avenue
 Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
1 2753854	Custodian Office - Sink	Water	0.001 mg/L
2 2753855	Water Fountain by 204 - Bubblers	Water	0.001 mg/L
3 2753856	Faculty Lounge - Sink	Water	BDL < 0.001 mg/L
4 2753857	Faculty Lounge - Sprayer Head	Water	0.001 mg/L
5 2753858	Room 220A Speech Room - Sink	Water	0.002 mg/L
6 2753859	Library Office Back Room - Sink	Water	BDL < 0.001 mg/L
7 2753860	Room 106 - Sink	Water	BDL < 0.001 mg/L
8 2753861	Room 107 - Sink	Water	BDL < 0.001 mg/L
9 2753862	Principals Office Bathroom - Sink	Water	0.001 mg/L

BDL = Below Detectable Limits


Liability Limited to Cost of Analysis

Results Applicable to Those Items Tested

Rhode Island DOH No. LAO00107 Massachusetts DOL No. A A 000072 Connecticut DOH No. PH-0622 Maine DEP No. LA-024 Vermont DOH No. AL-709936

Eastern Analytical Services, Inc.
Water Sample Report

RE: Edgemont - Seely Place School


Date Collected: 04/22/2021
 Collected By: Nicholas Coon
 Date Received: 04/23/2021
 Date Analyzed: 04/28/2021
 Analyzed By: Ernest Sanchez
 Signature: 
 Analyte: Pb Water
 Analytical Method: EPA 200.9
 NYS Lab Number: 10851

Client: RegCom
 245 Albany Avenue
 Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
10 2753863	Wate Fountain by 104 - Bubbler	Water	0.002 mg/L
11 2753864	Room 105 - Sink	Water	0.002 mg/L
12 2753865	Room 104 - Sink	Water	0.002 mg/L
13 2753866	Room 103 - Sink	Water	0.002 mg/L
14 2753867	Room Between 101 and 103 - Sink	Water	0.001 mg/L
15 2753868	Room Between 101 and 103 - Water Fountain (Bubbler)	Water	0.007 mg/L
16 2753869	Water Fountain by Room 109 - Bubbler	Water	0.004 mg/L
17 2753870	Room 109 - Sink	Water	0.001 mg/L
18 2753871	Science Lab Bathroom - Sink	Water	0.011 mg/L

Eastern Analytical Services, Inc.
Water Sample Report

RE: Edgemont - Seely Place School

Date Collected: 04/22/2021
 Collected By: Nicholas Coon
 Date Received: 04/23/2021
 Date Analyzed: 04/28/2021
 Analyzed By: Ernest Sanchez
 Signature: 
 Analyte: Pb Water
 Analytical Method: EPA 200.9
 NYS Lab Number: 10851

Client: RegCom
 245 Albany Avenue
 Thornwood, NY 10594


Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
19 2753872	Water Fountain by Room 113 - Bottle Filler	Water	BDL < 0.001 mg/L
20 2753873	Prep Room in Room 113 - Sink	Water	0.001 mg/L
21 2753874	Cafeteria - Water Fountain #2 (Bottle Filler)	Water	BDL < 0.001 mg/L
22 2753875	Cafeteria - Sink	Water	BDL < 0.001 mg/L
23 2753876	Band Room 002 - Sink	Water	0.006 mg/L
24 2753877	Girls Bathroom by 003 - Sink #2	Water	BDL < 0.001 mg/L
25 2753878	Rom 003 - Sink	Water	0.008 mg/L
26 2753879	Water Fountain by Room 006 - Bubbler	Water	0.001 mg/L
27 2753880	Room 008 - Sink	Water	0.004 mg/L

BDL = Below Detectable Limits
 Liability Limited to Cost of Analysis
 Results Applicable to Those Items Tested

Rhode Island DOH No. LAO00107 Massachusetts DOL No. A A 000072 Connecticut DOH No. PH-0622 Maine DEP No. LA-024 Vermont DOH No. AL-709936

Eastern Analytical Services, Inc. Water Sample Report

RE: Edgemont - Seely Place School

Date Collected: 04/22/2021
Collected By: Nicholas Coon
Date Received: 04/23/2021
Date Analyzed: 04/28/2021
Analyzed By: Ernest Sanchez
Signature: 
Analyte: Pb Water
Analytical Method: EPA 200.9
NYS Lab Number: 10851

Client: RegCom
245 Albany Avenue
Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
28 2753881	Room 007 - Sink	Water	0.002 mg/L
Blank 2753882	Not Applicable	Blank	BDL < 0.001 mg/L