


Eastern Analytical Services, Inc.
Water Sample Report

RE: CPN EDG-1035-16-IH - Edgemont UFSD - High School/Middle School - Admin Building

Date Collected: 04/01/2016
 Collected By: Ernest Coon
 Date Received: 04/01/2016
 Date Analyzed: 04/08/2016
 Analyzed By: Peter P. Argyrakis
 Signature: 
 Analyte: Pb Water
 Analytical Method EPA 200.9
 NYS Lab Number: 10851


Client: RegCom
 245 Albany Avenue
 Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
20A 2417556	Cafeteria Water Fountain	Water	BDL < 0.001 mg/L
20B 2417557	Cafeteria Water Fountain	Water	0.001 mg/L
21A 2417558	Teachers Lounge Sink	Water	0.001 mg/L
21B 2417559	Teachers Lounge Sink	Water	0.001 mg/L
22A 2417560	Kitchen Sink (Near Bathroom) - Sampled Sink on Right	Water	0.004 mg/L
22B 2417561	Kitchen Sink (Near Bathroom) - Sampled Sink on Right	Water	0.001 mg/L
23A 2417562	Kitchen Sink (Near Kitchen Office) - Sampled Sink on Right	Water	0.027 mg/L
23B 2417563	Kitchen Sink (Near Kitchen Office) - Sampled Sink on Right	Water	0.001 mg/L
24A 2417564	Kitchen Sink (Near Stove) - Sampled Sink on Right	Water	0.026 mg/L

BDL = Below Detectable Limits
 Liability Limited to Cost of Analysis
 Results Applicable to Those Items Tested

Eastern Analytical Services, Inc.
Water Sample Report

RE: CPN EDG-1035-16-IH - Edgemont UFSD - High School/Middle School - Admin Building


Date Collected: 04/01/2016
 Collected By: Ernest Coon
 Date Received: 04/01/2016
 Date Analyzed: 04/08/2016
 Analyzed By: Peter P. Argyrakis
 Signature: 
 Analyte: Pb Water
 Analytical Method EPA 200.9
 NYS Lab Number: 10851

Client: RegCom
 245 Albany Avenue
 Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
24B 2417565	Kitchen Sink (Near Stove) - Sampled Sink on Right	Water	0.001 mg/L
25A 2417566	Kitchen Sink (Near Tray Line) - Sampled Sink on Right	Water	0.044 mg/L
25B 2417567	Kitchen Sink (Near Tray Line) - Sampled Sink on Right	Water	0.003 mg/L
26A 2417568	Custodian's Office Sink	Water	BDL < 0.001 mg/L
26B 2417569	Custodian's Office Sink	Water	0.001 mg/L
27A 2417570	Hallway Water Fountain (Near Main Office)	Water	0.001 mg/L
27B 2417571	Hallway Water Fountain (Near Main Office)	Water	0.001 mg/L
28A 2417572	Gym Building - Hallway Water Fountain (Near Girls Bathroom)	Water	0.001 mg/L
28B 2417573	Gym Building - Hallway Water Fountain (Near Girls Bathroom)	Water	BDL < 0.001 mg/L

Eastern Analytical Services, Inc.
Water Sample Report

RE: CPN EDG-1035-16-IH - Edgemont UFSD - High School/Middle School - Admin Building

Date Collected: 04/01/2016
 Collected By: Ernest Coon
 Date Received: 04/01/2016
 Date Analyzed: 04/08/2016
 Analyzed By: Peter P. Argyrakis
 Signature: 
 Analyte: Pb Water
 Analytical Method EPA 200.9
 NYS Lab Number: 10851


Client: RegCom
 245 Albany Avenue
 Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
29A 2417574	Gym Building - Hallway Water Fountain (Near Boys Bathroom)	Water	BDL < 0.001 mg/L
29B 2417575	Gym Building - Hallway Water Fountain (Near Boys Bathroom)	Water	BDL < 0.001 mg/L
30A 2417576	Fitness Center Water Fountain	Water	BDL < 0.001 mg/L
30B 2417577	Fitness Center Water Fountain	Water	BDL < 0.001 mg/L
31A 2417578	Girls Locker Sink	Water	0.001 mg/L
31B 2417579	Girls Locker Sink	Water	BDL < 0.001 mg/L
32A 2417580	D Building - Hallway Water Fountain (Near Room D8)	Water	BDL < 0.001 mg/L
32B 2417581	D Building - Hallway Water Fountain (Near Room D8)	Water	BDL < 0.001 mg/L
33A 2417582	D Building - Room D8 Sink	Water	0.010 mg/L

BDL = Below Detectable Limits
 Liability Limited to Cost of Analysis
 Results Applicable to Those Items Tested

Eastern Analytical Services, Inc.
Water Sample Report

RE: CPN EDG-1035-16-IH - Edgemont UFSD - High School/Middle School - Admin Building

Date Collected: 04/01/2016
 Collected By: Ernest Coon
 Date Received: 04/01/2016
 Date Analyzed: 04/08/2016
 Analyzed By: Peter P. Argyrakis
 Signature: 
 Analyte: Pb Water
 Analytical Method EPA 200.9
 NYS Lab Number: 10851


Client: RegCom
 245 Albany Avenue
 Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
33B 2417583	D Building - Room D8 Sink	Water	0.001 mg/L
34A 2417584	D Building - Hallway Water Fountain (Near D2)	Water	BDL < 0.001 mg/L
34B 2417585	D Building - Hallway Water Fountain (Near D2)	Water	BDL < 0.001 mg/L
35A 2417586	E Building - Water Fountain (Near LGI)	Water	0.004 mg/L
35B 2417587	E Building - Water Fountain (Near LGI)	Water	0.003 mg/L
36A 2417588	E Building - Water Fountain in Library	Water	BDL < 0.001 mg/L
36B 2417589	E Building - Water Fountain in Library	Water	BDL < 0.001 mg/L
37A 2417590	E Building - Hallway Water Fountain - Upper E (Sampled Water Fountain Near Window)	Water	BDL < 0.001 mg/L
37B 2417591	E Building - Hallway Water Fountain - Upper E (Sampled Water Fountain Near Window)	Water	BDL < 0.001 mg/L

BDL = Below Detectable Limits
 Liability Limited to Cost of Analysis
 Results Applicable to Those Items Tested

Eastern Analytical Services, Inc.
Water Sample Report

RE: CPN EDG-1035-16-IH - Edgemont UFSD - High School/Middle School - Admin Building

Date Collected: 04/01/2016
 Collected By: Ernest Coon
 Date Received: 04/01/2016
 Date Analyzed: 04/08/2016
 Analyzed By: Peter P. Argyrakis
 Signature: 
 Analyte: Pb Water
 Analytical Method EPA 200.9
 NYS Lab Number: 10851


Client: RegCom
 245 Albany Avenue
 Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
38A 2417592	E Building - A School Sink	Water	BDL < 0.001 mg/L
38B 2417593	E Building - A School Sink	Water	BDL < 0.001 mg/L
39A 2417594	E Building - Hallway Water Fountain - Lower E (Sampled Water Fountain Near Room 013)	Water	0.001 mg/L
39B 2417595	E Building - Hallway Water Fountain - Lower E (Sampled Water Fountain Near Room 013)	Water	BDL < 0.001 mg/L
40A 2417596	A Building - Hallway Water Fountain - Near A17 (Close to Room A17)	Water	0.005 mg/L
40B 2417597	A Building - Hallway Water Fountain - Near A17 (Close to Room A17)	Water	0.001 mg/L
41A 2417598	A Building - Hallway Water Fountain - Near A17 (Near Alarm Room)	Water	0.002 mg/L
41B 2417599	A Building - Hallway Water Fountain - Near A17 (Near Alarm Room)	Water	BDL < 0.001 mg/L
42A 2417600	A Building - Hallway Water Fountain (Near Girls Bathroom)	Water	0.005 mg/L

BDL = Below Detectable Limits
 Liability Limited to Cost of Analysis
 Results Applicable to Those Items Tested

Eastern Analytical Services, Inc.
Water Sample Report

RE: CPN EDG-1035-16-IH - Edgemont UFSD - High School/Middle School - Admin Building


Date Collected: 04/01/2016
 Collected By: Ernest Coon
 Date Received: 04/01/2016
 Date Analyzed: 04/08/2016
 Analyzed By: Peter P. Argyrakis
 Signature: 
 Analyte: Pb Water
 Analytical Method EPA 200.9
 NYS Lab Number: 10851

Client: RegCom
 245 Albany Avenue
 Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
42B 2417601	A Building - Hallway Water Fountain (Near Girls Bathroom)	Water	0.001 mg/L
43A 2417602	B Building - Hallway Water Fountain (Near B4)	Water	0.001 mg/L
43B 2417603	B Building - Hallway Water Fountain (Near B4)	Water	BDL < 0.001 mg/L
44A 2417604	C Building - Hallway Water Fountain (Near Room C4)	Water	0.008 mg/L
44B 2417605	C Building - Hallway Water Fountain (Near Room C4)	Water	0.001 mg/L
45A 2417606	C Building - Room C1 (Has Brita H2O Filter Attached)	Water	0.044 mg/L
45B 2417607	C Building - Room C1 (Has Brita H2O Filter Attached)	Water	0.005 mg/L
46A 2417608	Administration Building - Nurses Office	Water	0.003 mg/L
46B 2417609	Administration Building - Nurses Office	Water	0.001 mg/L

Eastern Analytical Services, Inc.
Water Sample Report

RE: CPN EDG-1035-16-IH - Edgemont UFSD - High School/Middle School - Admin Building

Date Collected: 04/01/2016
Collected By: Ernest Coon
Date Received: 04/01/2016
Date Analyzed: 04/08/2016
Analyzed By: Peter P. Argyrakis
Signature: 
Analyte: Pb Water
Analytical Method EPA 200.9
NYS Lab Number: 10851

Client: RegCom
245 Albany Avenue
Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
47A 2417610	Administration Building - Band Room (1st One as You Enter Room)	Water	0.002 mg/L
47B 2417611	Administration Building - Band Room (1st One as You Enter Room)	Water	BDL < 0.001 mg/L
48A 2417612	Administration Building - Band Room (Plastic Sink)	Water	0.001 mg/L
48B 2417613	Administration Building - Band Room (Plastic Sink)	Water	0.001 mg/L
49 2417614	Not Applicable	Water Blank	0.004 mg/L