


Eastern Analytical Services, Inc.

Water Sample Report

RE: CPN EDG-1111-16-IH - Edgemont UFSD - Seely Place School

Date Collected: 09/17/2016
Collected By: Ernest Coon
Date Received: 09/17/2016
Date Analyzed: 09/21/2016
Analyzed By: Peter P. Argyrakis
Signature: 
Analyte: Pb Water
Analytical Method: EPA 200.9
NYS Lab Number: 10851


Client: RegCom
245 Albany Avenue
Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
1 2451910	Boiler Room Bathroom - Sink	Water	0.001 mg/L
2 2451911	Boiler Room Lunch Area - Sink	Water	BDL < 0.001 mg/L
3 2451912	Custodian's Office - Sink	Water	BDL < 0.001 mg/L
4 2451913	Boys Room - Sink #1 (From Left to Right) Next to Room LL1	Water	0.006 mg/L
5 2451914	Boys Room - Sink #2 (From Left to Right) Next to Room LL1	Water	0.005 mg/L
6 2451915	Custodial Closet - Sink - Next to Room 008	Water	0.008 mg/L
7 2451916	Room 008 - Sink	Water	0.006 mg/L
8 2451917	Art Room - Sink #1 Tap #1 (From Left to Right)	Water	0.011 mg/L
9 2451918	Art Room - Sink #1 Tap #3 (From Left to Right)	Water	0.002 mg/L

Eastern Analytical Services, Inc.

Water Sample Report

RE: CPN EDG-1111-16-IH - Edgemont UFSD - Seely Place School

Date Collected: 09/17/2016
Collected By: Ernest Coon
Date Received: 09/17/2016
Date Analyzed: 09/21/2016
Analyzed By: Peter P. Argyrakis
Signature: 
Analyte: Pb Water
Analytical Method: EPA 200.9
NYS Lab Number: 10851


Client: RegCom
245 Albany Avenue
Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
10 2451919	Art Room - Sink #1 Tap #4 (From Left to Right)	Water	0.008 mg/L
11 2451920	Art Room - Sink #2 Tap #1 (From Left to Right)	Water	0.006 mg/L
12 2451921	Art Room - Sink #2 Tap #3 (From Left to Right)	Water	0.010 mg/L
13 2451922	Art Room - Sink #2 Tap #4 (From Left to Right)	Water	0.009 mg/L
14 2451923	Coaches Office Next to Art Room - Sink	Water	0.010 mg/L
15 2451924	Girls Bathroom - Sink #1 - Near Art Room	Water	0.006 mg/L
16 2451925	Girls Bathroom - Sink #2 - Near Art Room	Water	0.005 mg/L
17 2451926	Girls Bathroom - Sink #1 - Near Room 003 (From Left to Right)	Water	0.001 mg/L
18 2451927	Girls Bathroom - Sink #2 - Near Room 003 (From Left to Right)	Water	BDL < 0.001 mg/L

Eastern Analytical Services, Inc.

Water Sample Report

RE: CPN EDG-1111-16-IH - Edgemont UFSD - Seely Place School

Date Collected: 09/17/2016
Collected By: Ernest Coon
Date Received: 09/17/2016
Date Analyzed: 09/21/2016
Analyzed By: Peter P. Argyrakis
Signature: 
Analyte: Pb Water
Analytical Method: EPA 200.9
NYS Lab Number: 10851


Client: RegCom
245 Albany Avenue
Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
19 2451928	Boys Bathroom - Sink - Near Room 003	Water	BDL < 0.001 mg/L
20 2451929	Classroom 003 (Science Lab) - Sink #1 (From Left to Right)	Water	BDL < 0.001 mg/L
21 2451930	Classroom 003 (Science Lab) - Sink #2 (From Left to Right)	Water	BDL < 0.001 mg/L
22 2451931	Classroom 003 (Science Lab) - Sink #3 (From Left to Right)	Water	0.001 mg/L
23 2451932	Classroom 003 (Science Lab) - Sink #4 (From Left to Right)	Water	0.001 mg/L
24 2451933	Classroom 002 - Sink	Water	0.015 mg/L
25 2451934	Lunch Room - Sink	Water	0.001 mg/L
26 2451935	Lunch Room Custodians Room - Slop Sink	Water	BDL < 0.001 mg/L
27 2451936	Library - Sink	Water	0.005 mg/L

Eastern Analytical Services, Inc.

Water Sample Report

RE: CPN EDG-1111-16-IH - Edgemont UFSD - Seely Place School

Date Collected: 09/17/2016
Collected By: Ernest Coon
Date Received: 09/17/2016
Date Analyzed: 09/21/2016
Analyzed By: Peter P. Argyrakis
Signature: 
Analyte: Pb Water
Analytical Method: EPA 200.9
NYS Lab Number: 10851


Client: RegCom
245 Albany Avenue
Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
28 2451937	Classroom 107 - Sink	Water	0.008 mg/L
29 2451938	Classroom 107 Bathroom - Sink	Water	0.001 mg/L
30 2451939	Classroom 106 - Sink	Water	0.001 mg/L
31 2451940	Classroom 106 Bathroom - Sink	Water	0.001 mg/L
32 2451941	Principal's Office Bathroom - Sink	Water	0.003 mg/L
33 2451942	Faculty Bathroom - Sink - Next to Principal's Office	Water	0.003 mg/L
34 2451943	Custodial Closet - Slop Sink	Water	0.001 mg/L
35 2451944	Boys Room Nex to Room 104 - Sink #1 (From Left to Right)	Water	0.003 mg/L
36 2451945	Boys Room Nex to Room 104 - Sink #2 (From Left to Right)	Water	0.003 mg/L

Eastern Analytical Services, Inc.

Water Sample Report

RE: CPN EDG-1111-16-IH - Edgemont UFSD - Seely Place School

Date Collected: 09/17/2016
Collected By: Ernest Coon
Date Received: 09/17/2016
Date Analyzed: 09/21/2016
Analyzed By: Peter P. Argyrakis
Signature: 
Analyte: Pb Water
Analytical Method: EPA 200.9
NYS Lab Number: 10851


Client: RegCom
245 Albany Avenue
Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
37 2451946	Boys Room Nex to Room 104 - Sink #3 (From Left to Right)	Water	0.004 mg/L
38 2451947	Classroom 104 - Sink	Water	0.004 mg/L
39 2451948	Classroom 104 Bathroom - Sink	Water	0.043 mg/L
40 2451949	Classroom 105 - Sink	Water	0.003 mg/L
41 2451950	Classroom 103 - Sink	Water	0.003 mg/L
42 2451951	Classroom 101 - Sink	Water	0.002 mg/L
43 2451952	Classroom 101 Bathroom - Sink	Water	0.002 mg/L
44 2451953	Classroom 102 - Sink	Water	0.001 mg/L
45 2451954	Girls Bathroom - Bathroom Off Vestibule - Sink	Water	0.005 mg/L

Eastern Analytical Services, Inc.

Water Sample Report

RE: CPN EDG-1111-16-IH - Edgemont UFSD - Seely Place School

Date Collected: 09/17/2016
Collected By: Ernest Coon
Date Received: 09/17/2016
Date Analyzed: 09/21/2016
Analyzed By: Peter P. Argyrakis
Signature: 
Analyte: Pb Water
Analytical Method: EPA 200.9
NYS Lab Number: 10851


Client: RegCom
245 Albany Avenue
Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
46 2451955	Girls Bathroom - Sink #1 (From Left to Right)	Water	0.006 mg/L
47 2451956	Girls Bathroom - Sink #2 (From Left to Right)	Water	0.004 mg/L
48 2451957	Girls Bathroom - Sink #3 (From Left to Right)	Water	0.015 mg/L
49 2451958	Classroom 109 - Sink	Water	0.009 mg/L
50 2451959	Nurse's Office - Sink	Water	0.004 mg/L
51 2451960	Nurse's Office Bathroom - Sink (Room 111)	Water	0.002 mg/L
52 2451961	Classroom 112 - Bathroom Sink	Water	0.022 mg/L
53 2451962	Classroom 113 - Sink	Water	0.003 mg/L
54 2451963	Custodian's Closet - Slop Sink	Water	0.003 mg/L

Eastern Analytical Services, Inc.

Water Sample Report

RE: CPN EDG-1111-16-IH - Edgemont UFSD - Seely Place School

Date Collected: 09/17/2016
Collected By: Ernest Coon
Date Received: 09/17/2016
Date Analyzed: 09/21/2016
Analyzed By: Peter P. Argyrakis
Signature: 
Analyte: Pb Water
Analytical Method: EPA 200.9
NYS Lab Number: 10851

Client: RegCom
245 Albany Avenue
Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
55 2451964	Faculty Bathroom - Sink - Near CR 219	Water	0.002 mg/L
56 2451965	Room 220A - Sink	Water	0.025 mg/L
57 2451966	Faculty Room - Room 215 - Sink	Water	0.001 mg/L
58 2451967	Faculty Bathroom - Sink - Near Classroom 219	Water	0.003 mg/L
59 2451968	Custodian's Closet - Sink - Near Classroom 219	Water	0.003 mg/L
60 2451969	Girls Bathroom - Sink #2 - Near Classroom 219 (From Left to Right)	Water	0.001 mg/L
61 2451970	Girls Bathroom - Sink #3 - Near CR 219 (From Left to Right)	Water	0.001 mg/L
62 2451971	Girls Bathroom - Sink #4 - Near CR 219 (From Left to Right)	Water	0.001 mg/L
63 2451972	Boys Bathroom - Bathroom Off Vestibule - Sink (Near Girls Room)	Water	0.008 mg/L

Eastern Analytical Services, Inc.

Water Sample Report

RE: CPN EDG-1111-16-IH - Edgemont UFSD - Seely Place School

Date Collected: 09/17/2016

Collected By: Ernest Coon

Date Received: 09/17/2016

Date Analyzed: 09/21/2016

Analyzed By: Peter P. Argyrakis

Signature: 

Analyte: Pb Water

Analytical Method: EPA 200.9

NYS Lab Number: 10851

Client: RegCom

245 Albany Avenue

Thornwood, NY 10594

Sample ID# / Lab ID#	Sample Location	Sample Notes	Concentration
64 2451973	Boys Bathroom - Sink #1 (From Left to Right)	Water	0.006 mg/L
65 2451974	Boys Bathroom - Sink #2 (From Left to Right)	Water	0.001 mg/L
66 2451975	Not Applicable	Water Blank	BDL < 0.001 mg/L

BDL = Below Detectable Limits

Liability Limited to Cost of Analysis

Results Applicable to Those Items Tested

AIHA Accreditation No. 418 Rhode Island DOH No. AAL-072T3 Massachusetts DOL No. A A 000072 Connecticut DOH No. PH-0622 Maine DEP No. LA-024 Vermont DOH No. AAS-2095