

Edgemont UFSD

High School/Middle School

Sample ID #	Sample Location	Date Sampled	Results (mg/L)	Compliant (Y/N)	Remedial Action
1	Administration Building - Boys Bathroom - Sink #2	4/20/21	0.001	Y	NA
2	Administration Building - Girls Bathroom - Sink #1	4/20/21	0.001	Y	NA
3	Administration Building - Nurses Office - Refridgerator Water Dispenser	4/20/21	BDL < 0.001	Y	NA
4	Administration Building - Nurses Office - Refridgerator Ice Maker	4/20/21	BDL < 0.001	Y	NA
5	Administration Building - Teachers Lounge - Sink	4/20/21	BDL < 0.001	Y	NA
6	Administration Building - Kitchen - Sink #1	4/20/21	0.003	Y	NA
7	Administration Building - Kitchen - Sink #2	4/20/21	0.001	Y	NA
8	Administration Building - Kitchen - Sink #3	4/20/21	0.003	Y	NA
9	Administration Building - Kitchen - Sink #4	4/20/21	0.037	Exceeded NYS AL Complaint As Posted	Sign posted in accordance with Lead Testing in School Drinking Water – 10 NYCRR Subpart 67-4
10	Administration Building - Cafeteria - Water Fountain (Bottle Filler)	4/20/21	0.001	Y	NA
11	Building D - 1st Floor - Water Fountain (Bottle Filler)	4/20/21	BDL < 0.001	Y	NA
12	Building D - 2nd Floor - Water Fountain (Bottle Filler)	4/20/21	BDL < 0.001	Y	NA
13	Building D - Chemistry Prep Room - sink	4/20/21	0.012	Y	NA
14	Building D - AV Room Offices - sink	4/20/21	0.003	Y	NA
15	Buiding E - 1st Floor Boys Bathroom - Sink #2	4/20/21	0.001	Y	NA
16	Buiding E - 1st Floor Boys Bathroom - Sink #3	4/20/21	BDL < 0.001	Y	NA
17	Buiding E - 1st Floor Girls Bathroom - Sink #1	4/20/21	BDL < 0.001	Y	NA
18	Buiding E - 1st Floor Water Fountain (Bubbler) - Left Side	4/20/21	0.004	Y	NA
19	Buiding E - 1st Floor Water Fountain (Bubbler) - Right Side	4/20/21	BDL < 0.001	Y	NA
20	Buiding E - Library - Water Fountain (Bottle Filler)	4/20/21	BDL < 0.001	Y	NA
21	Buiding E - Library - Sink	4/20/21	0.003	Y	NA
22	Buiding E - 2nd Floor Water Fountain #1 (Bubbler)	4/20/21	BDL < 0.001	Y	NA
23	Buiding E - 2nd Floor Water Fountain #2 (Bubbler)	4/20/21	BDL < 0.001	Y	NA

24	Buiding E - "A" School Room 112 - Sink	4/20/21	BDL < 0.001	Y	NA
25	Buiding A - 1st Floor Boys Bathroom - Sink #2	4/20/21	BDL < 0.001	Y	NA
26	Buiding A - 1st Floor Boys Bathroom - Sink #3	4/20/21	0.009	Y	NA
27	Buiding A - 1st Floor Girls Bathroom - Sink #2	4/20/21	0.002	Y	NA
28	Buiding A - 1st Floor Girls Bathroom - Sink #3	4/20/21	BDL < 0.001	Y	NA
29	Buiding A - 1st Floor Water Fountain (Bubbler)	4/20/21	0.006	Y	NA
30	Buiding A - 1st Floor Water Fountain (Bubbler)	4/20/21	0.003	Y	NA
31	Building B - 1st Floor - Water Fountain (Bubbler)	4/20/21	0.001	Y	NA
32	Building B - 1st Floor Girls Bathroom - Sink #2	4/20/21	BDL < 0.001	Y	NA
33	Building B - Room B2 - Prep Room - Sink	4/20/21	0.008	Y	NA
34	Building B - 1st Floor Boys Bathroom - Sink #1	4/20/21	BDL < 0.001	Y	NA
35	Building C - Womens Bathroom - Sink #1	4/20/21	0.003	Y	NA
36	Building C - Hallway - Water Fountain (Bubbler)	4/20/21	0.001	Y	NA
37	Building C - Boys Bathroom - Sink #2	4/20/21	0.003	Y	NA
38	Building C - C1 Prep Room - Sink	4/20/21	0.005	Y	NA
39	Administration Building - Kitchen Ice Machine	4/20/21	BDL < 0.001	Y	NA
40	Gymnasuim Building - Concessions Room - Ice Machine	4/20/21	BDL < 0.001	Y	NA
41	Gymnasuim Building - Concessions Room - Sink	4/20/21	BDL < 0.001	Y	NA
42	Gymnasuim Building - Hallway - Water Fountain (bottle Filler)	4/20/21	BDL < 0.001	Y	NA
43	Gymnasuim Building - Womens Bathroom Near Hallway - Sink #2	4/20/21	0.001	Y	NA
44	Gymnasuim Building - Hallway Near Mens Bathroom- water Fountain (Bubbler)	4/20/21	BDL < 0.001	Y	NA
45	Gymnasuim Building - Mens Bathroom Near Hallway - Sink #1	4/20/21	BDL < 0.001	Y	NA
46	Gymnasuim Building - Boys Locker Room - Water Fountain (Bubbler)	4/20/21	BDL < 0.001	Y	NA
47	Gymnasuim Building - Girls Locker Room - Water Fountain (Bubbler)	4/20/21	BDL < 0.001	Y	NA
48	Facilities Directors Office - Sink	4/20/21	0.006	Y	NA
49	Field House - Outdoor Field - Water Fountain (Bubbler)	4/20/21	BDL < 0.001	Y	NA
50	Field House - Outdoor Field - Water Fountain (Bottler Filler)	4/20/21	BDL < 0.001	Y	NA
51	Field House - Outdoor Field Box (Far Side)- Spigot #1	4/20/21	BDL < 0.001	Y	NA
52	Field House - Outdoor Field Box (Far Side)- Spigot #2	4/20/21	0.006	Y	NA
53	Field House - Outdoor Field Box (Bleacher Side)- Spigot #3	4/20/21	BDL < 0.001	Y	NA
54	Field House - Outdoor Field Box (Bleacher Side)- Spigot #4	4/20/21	BDL < 0.001	Y	NA
57	Administration Building - Kitchen - Kettle Spigot	4/20/21	BDL < 0.001	Y	NA

58	Gymnasium - Boys Locker Room Bathroom - Sink #1	4/20/21	BDL < 0.001	Y	NA
59	Gymnasium - Girks Locker Room Bathroom - Sink #1	4/20/21	0.001	Y	NA
60	Gymnasium - Girks Locker Room Bathroom - Sink #2	4/20/21	0.003	Y	NA
61	Gymnasium - Girks Locker Room Bathroom - Sink #3	4/20/21	0.006	Y	NA
62	Field House - Outdoor Tennis Courts - Water Fountain (Bubbler)	4/21/21	0.003	Y	NA
63	Field House - Outdoor Tennis Courts - Spigot	4/21/21	0.002	Y	NA
64	Blank	4/20/21	BDL < 0.001	Y	NA

NA = Not Applicable

NYS Lead Action Level 0.015 mg/L

Sinks are counted from Left to Right

Edgemont UFSD

Greenville Elementary School

Sample ID #	Sample Location	Date Sampled	Results (mg/L)	Compliant (Y/N)	Remedial Action
1	Boys Bathroom by A1 - Sink #2	4/21/21	BDL <0.001	Y	NA
2	Girls Bathroom by A1 - Sink #2	4/21/21	0.001	Y	NA
3	Small Office Between Room A1 and A3 - Sink	4/21/21	0.002	Y	NA
4	Classroom A6 - Sink	4/21/21	BDL <0.001	Y	NA
5	Classroom A5 - Sink	4/21/21	BDL <0.001	Y	NA
6	Classroom A8 - Sink	4/21/21	0.009	Y	NA
7	Classroom A7 - Sink	4/21/21	BDL <0.001	Y	NA
8	Classroom A10 - Sink	4/21/21	0.003	Y	NA
9	Classroom A9 - Sink	4/21/21	0.001	Y	NA
10	Classroom A12 - Sink	4/21/21	0.001	Y	NA
11	Classroom A11 - Sink	4/21/21	0.001	Y	NA
12	Classroom A11 - Bubler	4/21/21	0.027	N	Removed From Service
13	Gym Boys Bathroom - Sink	4/21/21	0.001	Y	NA
14	Gym Bathroom Outside A15 - Sink	4/21/21	0.001	Y	NA
15	Boys Bathroom Room 154 - Sink #2	4/21/21	0.003	Y	NA
16	Boys Bathroom Room 154 - Sink #3	4/21/21	0.001	Y	NA
17	Library Office - Sink	4/21/21	BDL <0.001	Y	NA
18	Girls Bathroom Room 148 - Sink #1	4/21/21	BDL <0.001	Y	NA
19	Girls Bathroom Room 148 - Sink #2	4/21/21	BDL <0.001	Y	NA
20	Water Fountain Near All Purpose Room - Bottler Filler	4/21/21	BDL <0.001	Y	NA
21	Classroom C7 - Sink	4/21/21	BDL <0.001	Y	NA
22	Classroom C10 - Sink	4/21/21	BDL <0.001	Y	NA
23	Classroom C5 - Sink	4/21/21	BDL <0.001	Y	NA
24	Classroom C8 - Sink	4/21/21	BDL <0.001	Y	NA
25	Classroom C6 - Sink	4/21/21	BDL <0.001	Y	NA
26	Classroom C3 - Sink	4/21/21	0.005	Y	NA

27	Classroom C1 - Sink	4/21/21	0.017	Exceeded NYS AL Complaint As Posted	Sign posted in accordance with Lead Testing in School Drinking Water – 10 NYCRR Subpart 67-4
28	Kitchen Near Cafeteria - Sink	4/21/21	0.001	Y	NA
29	Water Fountain Near Boiler Room Door - Bottler Filler	4/21/21	BDL <0.001	Y	NA
30	Faculty Room - Sink	4/21/21	0.001	Y	NA
31	Faculty Room - Sink Sprayer	4/21/21	0.003	Y	NA
32	Classroom B1 - Sink	4/21/21	0.001	Y	NA
33	Classroom B3 - Sink	4/21/21	0.001	Y	NA
34	Bathroom Between Room B1 and B3 - Sink #2	4/21/21	0.001	Y	NA
35	Classroom B5 - Sink	4/21/21	BDL <0.001	Y	NA
36	Classroom B7 - Sink	4/21/21	BDL <0.001	Y	NA
37	Bathroom Between Room B5 and B7 - Sink #2	4/21/21	0.001	Y	NA
38	Classroom B8 - Sink	4/21/21	0.006	Y	NA
39	Blank	4/21/21	BDL <0.001	Y	NA

NA = Not Applicable

NYS Lead Action Level (AL) 0.015 mg/L

Sinks are counted from Left to Right

Edgemont UFSD

Seely Place School

Sample ID #	Sample Location	Date Sampled	Results (mg/L)	Compliant (Y/N)	Remedial Action
1	Custodial - Sink	4/22/21	0.001	Y	NA
2	Water Fountain Near Room 204 - Bubbler Only	4/22/21	0.001	Y	NA
3	Faculty Lounge - Sink	4/22/21	BDL <0.001	Y	NA
4	Faculty Lounge - Sprayer Head	4/22/21	0.001	Y	NA
5	Room 220A (Speech Room) - Sink	4/22/21	0.002	Y	NA
6	Library Office (Back Room) - Sink	4/22/21	BDL <0.001	Y	NA
7	Room 106 - Sink	4/22/21	BDL <0.001	Y	NA
8	Room 107 - Sink	4/22/21	BDL <0.001	Y	NA
9	Principals Office Bathroom - Sink	4/22/21	0.001	Y	NA
10	Water Fountain Near Room 104 - Bubbler Only	4/22/21	0.002	Y	NA
11	Room 105 - Sink	4/22/21	0.002	Y	NA
12	Room 104 - Sink	4/22/21	0.002	Y	NA
13	Room 103 - Sink	4/22/21	0.002	Y	NA
14	Room Between Room 101 and 103 - Sink	4/22/21	0.001	Y	NA
15	Room Between Room 101 and 103 - Water Fountain (Bubbler Only)	4/22/21	0.007	Y	NA
16	Water Fountain Near Room 109 - Bubbler Only	4/22/21	0.004	Y	NA
17	Room 109 - Sink	4/22/21	0.001	Y	NA
18	Science Laboratory Bathroom - Sink (ROOM #?)	4/22/21	0.011	Y	NA
19	Water Fountain Near Room 113 - Bottle Filler Only	4/22/21	BDL <0.001	Y	NA
20	Room 113 (Prep Room) - Sink	4/22/21	0.001	Y	NA
21	Cafeteria - Water Fountain #2 (Bottle Filler)	4/22/21	BDL <0.001	Y	NA
22	Cafeteria - Sink	4/22/21	BDL <0.001	Y	NA
23	Band Room 002 - Sink	4/22/21	0.006	Y	NA
24	Girls bathroom Near Room 003 - Sink #2	4/22/21	BDL <0.001	Y	NA
25	Room 003 - Sink	4/22/21	0.008	Y	NA
26	Water Fountain Near Room 006 - Bubbler	4/22/21	0.001	Y	NA
27	Room 008 - Sink	4/22/21	0.004	Y	NA
28	Room 007 - Sink	4/22/21	0.002	Y	NA
29	Blank	4/22/21	BDL <0.001	Y	NA

NA = Not Applicable

NYS Lead Action Level 0.015 mg/L

Sinks are counted from Left to Right